

DrägerService®

Dräger

## TECHNICAL SERVICE BULLETIN # 169

<b>Product:</b>	Narkomed MRI
<b>Date:</b>	June 23, 2000
<b>Reference Doc:</b>	SP00198
<b>Distribution:</b>	All Authorized Service Organizations, DrägerService
<b>Reason/Rationale:</b>	Dräger Medical Inc. (DMI) has released a modification to update the copper piping connected to the vaporizer manifold block on all existing Narkomed MRI units in the field prior to serial number 10143.
<b>Solution/Procedure:</b>	<p>Complete Field Service Procedure SP00198 on all field NM MRI units prior to serial number 10143.</p> <p>Upon completion of SP00198 on each NM MRI, complete a return form located in SP00198 and promptly forward to DrägerService via fax or by mail.</p>
<b>Timing/When:</b>	Machines to be modified and forms returned by July 24, 2000.
<b>Costs:</b>	<p>Labor - Warranty</p> <p>Parts - Kit is supplied at no charge</p>
<b>Ordering Info/Parts:</b>	<p>Order 1 each/unit, Kit -Vapor Block Pipes, Part number - 4116615</p> <p>Contact your CSR to process order. Reference TSB # 169 and machine serial number on Purchase Order.</p>

**If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789.**